



BE SURE VENTED LOOP
DUCKBILL IS INSTALLED
PROPERLY POINTING
DOWN.